



BRR housing project



Untreated wastewater dumped behind houses



Above: Poorly constructed wetland system
ARC ARC/BRCS Wetland system, no plants



ARC ARC/BRCS Wetland system, no plants



Above: Half of this ARC/BRCS wetland & vegetated leachfield system has been concreted over rendering it non-functional.

Below: This ARC/BRCS wetland & vegetated leachfield system was constructed *under* a house making it non-functional.



Below: This ARC/BRCS system has few plants meaning it will not function properly

