

BEFORE

NGO:
Swiss CARITAS
Project: Sumatra,
600 relocation houses
Problem: These new
communities are flood-
prone but drainage
canals are collapsing
because of highly
unstable peat soils...
*The area is recently
cleared peat forest*

The Photoshop image below was used,
in trainings, to illustrate to community
members what the area could look like
with proper planting and management.

AFTER

Photoshop Image

Solution:
Vetiver Bioengineering

www.vetiver-indonesia.com

Supplied:
Village Trainings
200,000 Vetiver Plants
Technical Specifications